

Dear Mr. Clarke:

I am pleased to notify you that your 8.0-hour Inspection Authorization (IA) refresher course titled, "**Honeywell GTCP36 Series APU Familiarization**" has been accepted. As of this date a review of the materials you submitted for this course meets the requirements of Title 14 of the Code of Federal Regulations (14 CFR) part 65, § 65.93(a)(4) for IA renewal.

Your FAA-accepted Training Course Number is **C-IND-IM-240613-K-022-004** and will expire June 30, 2028.

Your course will remain as an active course on the Master IA Refresher Course Database located on the www.FAASafety.gov website (Maintenance Hangar tab) for 48 months. The course may be withdrawn if it is discovered that your course no longer complies with § 65.93(a)(4).

Before the end of the 48 calendar-month period you must provide the IA Refresher Course Coordinator (IA RCC) with a request for course renewal acceptance in accordance with current guidelines. If you do not provide a request to renew your course acceptance with sufficient prior notice, at least 30 days prior to expiration, your course may be marked as expired in the Master IA Refresher Course Database.

As a provider of an FAA-accepted IA training course, you must continuously comply with current FAA guidance for your course acceptance number to remain valid. Please ensure the training completion certificates contain the information required in the guidance to avoid problems at time of IA renewal. This also requires you to notify the responsible Flight Standards office manager and the appropriate FAA Safety Team (FAAS Team) Program Manager (FPM) nearest the location of your training about the date, time, and location 30 days prior to presenting this course by letter, fax, and/or email. In addition, you should allow, at no charge, a minimum of one Flight Standards aviation safety inspector (ASI) from the responsible Flight Standards office for the purpose of oversight and/or the FAAS Team representative for the area where the training will take place. You should maintain a list of attendees and contact addresses for each course given for at least 36 months after the date the training was provided. Make this list available to any FAA office upon request. If it is determined that your course does not meet the guidelines, you will receive notification.

Congratulations, and thank you for your interest in aviation safety. Should you have further questions, please contact me at 9-AFS-IARefresher@faa.gov.

Sincerely,

Colby Barron
IA Refresher Course Coordinator (IA RCC)
Aircraft Maintenance Division
800 Independence Ave. SW
Washington, DC 20591